

096486319 • 050301

FIG. 1






FIG. 3






FIG. 4




FIG. 5

00489860 603050 "1301




FIG. 6




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 7E




FIG. 7F




FIG. 7G








FIG. 7I

FIG. 7J

FIG. 7K

FIG. 7L

09 14-2003 10:50 015030303




FIG. 8

10203050488915 008860





FIG. 9

FIG. 10A



CIRCUMFERENCE OF
STENT




FIG. 10B

106